

Bras d'essuie glace Ford / New Holland

Cette pièce remplace la référence constructeur 82030972



Référence : 128646

Prix : 35.40€

Critères associés :

Marque : Ford, New Holland

Bras d'essuie glace Ford / New Holland

Montage sur

Ford New Holland**T6000 Series**

T6010, T6020 Elite, T6020 Plus, T6030 Elite, T6030 Plus, T6030 Power Command, T6030 Range Command, T6040 Elite, T6050, T6050 Elite, T6050 Plus, T6050 Power Command, T6050 Range Command, T6060 Elite, T6070 Elite, T6070 Plus, T6070 Power Command, T6070 Range Command, T6080 Power Command, T6080 Range Command, T6090 Power Command, T6090 Range Command **T7000 Series**
T7030, T7030 Autocommand, T7030 Power Command, T7040 Autocommand, T7050, T7050 Autocommand, T7050 Power Command, T7060, T7060 Autocommand, T7060 Power Command, T7070 Autocommand **TSA Series**

TS100 A Deluxe, TS100 A Plus, TS115 A, TS115 A Delta, TS115 A Deluxe, TS115 A Plus, TS125 A Deluxe, TS125 A Plus, TS135 A Deluxe, TS135 A Plus **T7 Series**

T7.150, T7.170 Auto Command, T7.170 Power Command, T7.170 Range Command, T7.175, T7.180, T7.185 Auto Command, T7.185 Power Command, T7.185 Range Command, T7.190, T7.200 Auto Command, T7.200 Power Command, T7.200 Range Command, T7.210, T7.210 Auto Command, T7.210 Power Command, T7.210 Range Command, T7.220, T7.230, T7.230 Classic, T7.230 Sidewinder, T7.235, T7.245, T7.245 Auto Command, T7.245 Classic, T7.245 Sidewinder, T7.250, T7.250 Auto Command, T7.260, T7.260 Auto Command, T7.260 Classic, T7.260 Sidewinder, T7.270 Auto Command **T6 Series**
T6.120, T6.140, T6.140 Auto Command, T6.145 Auto Command, T6.150, T6.150 Auto Command, T6.155, T6.155 Auto Command, T6.160, T6.160 Auto Command, T6.165, T6.165 Auto Command, T6.175, T6.175 Auto Command

[Lien vers la fiche du produit](#)