

Pochette de joints supérieurs

Cette pièce remplace les références 3118124R91 02101487 4223005M91, 3637363M91, 4224292M91, 4224189M91, 4224369M1, 4224292V91, 68248, 747169M91, 4224369V1, 4224189Z91, 747169M92, 4224189V91, U5LT0065, 3637363M91, 3637444M91, 2521A601, 94429, U5LT0007, U5LT0059, 189297, 194429, 192427, U5LT0176, U5LT0174, U5LT0060, U5LT0065, U5LT0015, 189296, 89258, 89261, 89297, 168250, 89298, 85780, 40001, U5LT0016, 92427, 82890, 68250, 68248, 89296, 89262, 89263, 89265



Référence : 126768

Prix : 44.40€

Critères associés :

Marque : Landini, Massey Ferguson, Perkins, Volvo

Descriptif :

Pochette de joints supérieurs

Allis Chalmers : 170, 175

Landini / 6500, 6530, 6550, 6560, 6830, 6840, 6860, 6870, 6880, 7000, 7500, 7530, 7550, 7560, 7830, 7860, 7870, 7880, 8500, 8530, 8550, 8560, 8830, 8860, 8880, Blizzard 65, Blizzard 75, Blizzard 85, C6500, C6830, C7800, C7830, Rex 65, Rex 75, Rex 85, Trekker 75, Trekker 85

Massey Ferguson : 165, 168, 174, 174C, 175, 175 US Built, 178, 184, 185, 188, 194, 194C, 240, 255, 261, 265, 273, 274, 274SK, 275, 283, 284, 285, 285 US Built, 285S, 290, 290 Brazilian, 290 US Built, 293, 294, 294-4, 3050, 3060, 362, 365, 372, 373, 374, 375, 375E Brazilian, 377, 382, 383, 384, 387, 390, 390E

Brazilian, 393, 394, 397, 50, 50B, 50C, 50E, 50EX, 50H, 50HX, 565, 575, 590, 6000, 60H, 675, 690

Perkins : A4.212, A4.236, A4.248, A4.248.2

Volvo : 2200, 2204, 2250, 2254, T500

[Lien vers la fiche du produit](#)